



ofc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

U.S. Patent No.: US 6,953,957 B2

Serial No. : 10/684,584

Filed : October 15, 2003

Issued : October 11, 2005

For : CHARGE TRANSPORT MATERIAL INCLUDING A POLY-3,3"-DIALKYL-
2,2':5'2"-TERTHIOPHENE

**PETITION FOR CERTIFICATE OF CORRECTION
PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323**

*Certificate
JAN 12 2006
of Correction*

Assistant Commissioner for Patents
Washington, D. C. 20231

Sir:

Applicants hereby request that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction.

I. C.F.R. § 1.322

- The mistake was incurred through the fault of the Patent and Trademark Office and is clearly disclosed in the records of the Office. Therefore, no fee is due.

II. C.F.R. § 1.323


- At least some of the mistakes was/were made by the applicant. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

Enclosed herewith is a Form PTO-1050 (in duplicate) listing an error that has been found in the above-identified patent. The error is of a clerical or typographical nature or of minor character and was made in good faith. The requested correction does not constitute new matter or require reexamination.

JAN 13 2006

III. Accordingly, patentees and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.

Respectfully submitted,


Anthony J. Zelano, Reg. No. 27,969
Attorney for Applicants

MILLEN, WHITE, ZELANO
& BRANIGAN, P.C.
Arlington Courthouse Plaza 1
2200 Clarendon Blvd. Suite 1400
Arlington, Virginia 22201
Telephone: (703) 243-6333
Facsimile: (703) 243-6410

Attorney Docket No.: MERCK-2761

Date: January 10, 2005

JAN 13 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : US 6,953,957 B2

DATED : October 11, 2005

INVENTOR(S) : Iain McCULLOCH et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 6, line 47 reads "3,31'-disubstituted" should read --3,3"-disubstituted --

MAILING ADDRESS OF SENDER: Millen, White, Zelano & Branigan, P.C.
2200 Clarendon Blvd. Suite #1400
Arlington, VA 22201

PATENT NO. 6,953,957

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

JAN 13 2006